

ILLEGIB

[REDACTED]		25X1A
[REDACTED]		25X1A
DATE OF CONTENT	[REDACTED]	25X1X
DATE OBTAINED	[REDACTED] 25X1X	DATE PREPARED 9 October 1950
REFERENCES	[REDACTED]	25X1A
PAGES	1	ENCLOSURES (NO. & TYPE)
REMARKS	<p>RETURN TO CIA LIBRARY</p> <p>810 432</p>	

SOURCE

25X1X

1. The Gdynia-Babiedoly (Q 55/Y 45) airfield was surrounded by a restricted area of approximately 4x6 km. The I Bn of the 3rd Polish AF Engr Regt (CO Polish soldiers, 430 PWs and 40 women) was assigned to construction work at the field.
2. There was an EW runway, about 60x1,000 meters, and a SE-W runway, 80x1,600 meters. Both runways had a concrete base, 5 to 10 cm thick and an asphalt surface of 3 cm. A concrete parking site of 100x200 meters was in front of the hangars. From this parking site a concrete taxiway about 30 meters wide ran to the eastern side of the EW runway and to the south end of the SE-W runway. Another taxiway, about 20 meters wide, paralleled the EW runway and had several connecting lanes.
3. The following buildings and installations were at the field:
Three hangars, one of which had been dismantled at the Langenau airfield near Breslau (P 52/C 52) in the fall of 1947; several wooden and stone buildings and workshops; and a flight control station with a weather station, a mobile DF station. The lighting facilities were still destroyed in February 1946 but it was observed that cables were hauled to the field. *

25X1X

* [REDACTED] Comment. Confirms previous statements on the field and its installations. [REDACTED] More recent statements on the occupation of the field have been received. See [REDACTED]

25X1A

25X1A

Document No.	3
No Change in Class.	<input checked="" type="checkbox"/>
<input type="checkbox"/> Declassified	
Class. Changed To:	TS S C
Auth:	HR 70-2
Date:	270678
By:	034

CLASSIFICATION

CONFIDENTIAL/CONTROL/US OFFICIALS ONLY